

CASE NO.	Type of Hearing	Address	Type of Dwelling	SSL	Owner	May 27, 2015 Board Decision	Comments/Notes
08-096	Status Update	1303 Maple View PI SE	3 sty, det, s/f, frame	<u>5803-0892</u>	Thomara Speight	<input type="checkbox"/> Condemned <input type="checkbox"/> _____ Extension <input type="checkbox"/> Render Sanitary <input type="checkbox"/> Close (RS by Owner/DCRA) <input type="checkbox"/> Raze <input type="checkbox"/> Other/Referral _____	<p>Current Classification Status: Registered Blight 01/23/2014</p> <p>Last Inspection Date/Results: The property was deemed Blight 11/21/2013. A 13 point inspection was conducted 05/23/2014 and a NOV was issued. A Reinspection is scheduled for 10/10/2014. A Notice of Infraction was submitted 07/29/2014. A reinspection is scheduled for 05/20/2015.</p> <p>Last BCIB Board Action: A Certificate of Condemnation was placed on the property 11/21/2013. A 90 day extension was granted 02/25/2015 to give Mr. Speight time to get a complete engineer report. The demo permit has already been issued.</p>
12-025	Status Update	5102 Hanna PI SE	2 sty, semi det, masonry,	<u>5342E-0013</u>	Evelyn C. Brown Trustees	<input type="checkbox"/> Condemned <input type="checkbox"/> _____ Extension <input type="checkbox"/> Render Sanitary <input type="checkbox"/> Close (RS by Owner/DCRA) <input type="checkbox"/> Raze <input type="checkbox"/> Other/Referral _____	<p>Current Classification Status: Blight 10/25/2013</p> <p>Last Inspection Date/Results: A 13 point inspection is scheduled for 02/18/2015.</p> <p>Last BCIB Board Action: Notice to Show Cause and a scheduled meting notice was sent 12/19/2011. Ownership is still the same.</p>
15-004	Status Update	1311 Maple View PI SE	2 stry, det, frame	<u>5803-0883</u>	African Cultural Foundation Inc./Mohames Sesay, Jr.	<input type="checkbox"/> Condemned <input type="checkbox"/> _____ Extension <input type="checkbox"/> Render Sanitary <input type="checkbox"/> Close (RS by Owner/DCRA) <input type="checkbox"/> Raze <input type="checkbox"/> Other/Referral _____	<p>Current Classification Status: Blight 11/26/2013</p> <p>Last Inspection Date/Results: A 13 point inspection is scheduled for 02/18/2015.</p> <p>Last BCIB Board Action: A Notice to Show Cause was sent out 02/06/2015 and a 60 day extension was granted to allow time for reponse. There was none.</p>
12-058	Status Update	1014 Park Rd NW	2 sty, semi detached frame,s/f,	<u>2841-0110</u>	Albert M. Duncombe	<input type="checkbox"/> Condemned <input type="checkbox"/> _____ Extension <input type="checkbox"/> Render Sanitary <input type="checkbox"/> Close (RS by Owner/DCRA) <input type="checkbox"/> Raze <input type="checkbox"/> Other/Referral _____	<p>Current Classification Status: Blighted 01/30/2014</p> <p>Last Inspection Date/Results: A 13 point inspection was scheduled for 05/26/21015 and a NOV was issued.</p> <p>Last BCIB Board Action: A NTSC was sent out 03/19/2012. Ownership is different however the previous owner and current owner of record have the same last name. Accoridng to Lexus Nexus the current owner of record is deceased.</p>
15-007	New Case	434 19th St NE	2 sty, row, frame	<u>4547-0090</u>	Mae L. Hill	<input type="checkbox"/> Condemned <input type="checkbox"/> _____ Extension <input type="checkbox"/> Render Sanitary <input type="checkbox"/> Close (RS by Owner/DCRA) <input type="checkbox"/> Raze <input type="checkbox"/> Other/Referral _____	<p>Current Classification Status: Vacant 03/09/2015</p> <p>Last Inspection Date/Results: A 13 point inspection is scheduled for 05/26/2015.</p> <p>Last BCIB Board Action: New Case.</p>

